

- 4=6MM X 25MM BOLTS-A
- 4=6MM X 35MM BOLTS-B
- 12=1/4 USS WASHERS-C
- 2=1/4 LOCK NUTS-D
- 2=1/4 X 1 1/4 BOLTS-E
- 6=6MM X 40MM BOLTS-F



#SP131-STL

HONDA RANCHER 420IRS 2010

MUST REMOVE ALL THE STOCK PLASTIC SKID PLATES.

REPLACE THESE BOLTS THAT WERE REMOVED ON THE STOCK PLASTIC GUARDS.

2=1/4 X 1 1/4 BOLTS
2=1/4 LOCK NUTS
2= 1/4 USS WASHERS

2=6MM X 40MM BOLTS
2= 1/4 USS WASHERS

2=6MM X 40MM BOLTS
2= 1/4 USS WASHERS

2=6MM X 25MM BOLTS
2= 1/4 USS WASHERS

2=6MM X 25MM BOLTS
2= 1/4 USS WASHERS

2=6MM X 40MM BOLTS
2= 1/4 USS WASHERS

