



- 4=1/4 X 3/4 U-BOLTS-A
- 8=1/4 LOCK NUTS-B
- 8=1/4 USS WASHERS-C
- 1=5/16 SAE WASHER-D
- 1=8MMX1.25X50MM BOLT-E
- 1=1 3/8" SPACER-F

MUST REMOVE THE FRONT PLASTIC BUMPER TO INSTALL THE PLATE AND THE WINCH INTO THE FRONT CAVITY OF MACHINE. REPLACE THE BUMPER ON THE MACHINE ONCE COMPLETE.

# # 298139-R120

ARCTIC CAT 366 4X4

PLACE THE WINCH AND PLATE INTO THE CAVITY BEFORE TRYING TO BOLT THE PLATE TO THE FRAME. THEN PROCEED TO MOUNT THE PLATE TO THE FRAME AND THEN MOUNT THE WINCH TO THE PLATE. USE THE 1/4 U-BOLTS 1/4 WASHERS AND 1/4 LOCK NUTS.

REMOVE THIS STOCK 8MM BOLT AND USE THE 1 3/8" SPACER 8MMX1.25X50MM BOLT AND 5/16 SAE WASHER TO MOVE THE FENDER BRACE AWAY FROM THE ROTATING SWITCH ON WINCH.

MAY HAVE TO ROTATE THE MOTOR LEADS TO CLEAR THE FENDER BRACE. THIS IS ONLY ON THE WARN 3000LB.

